



## Wiring Diagram for Aerator Electric Motors

**ZH-286**  
3Phase/60HZ /440V



**ZHS-H24**  
1Phase/60HZ /440V



**Advertencia:** La conexión está configurada de fábrica para acoplar los arrancadores magneticos incluidos de fábrica TECO-Westinghouse

ZH-286: If the motor reverse, you can change R and S; or S and T; or R and T.

ZHS-H24: If the motor reverse, you can change the red line of motor NO.5 and NO.6